

# **Bus shelter**

## **Non-confidential**

Report by: Parish Clerk

Date: 05/05/26

Report to: Parish Council 05/2026

---

Following the Parish Council meeting in April, a local builder was contacted to survey the current state of the bus shelter.

### **Bus shelter condition report from builder one**

*As you can see from photos the backside of the concrete lintel support the steel inside of the concrete lintel supporting the roof is rusting and blowing the concrete which has caused a very weak spot and a large patch of then concrete lintel is missing which the roof structure is supported from this lintel which means the roof will need totally dismantling, rear wall of the shelter is pushing over so this will need to be taken down and rebuilt which means we can rebuild to the above and use the new rear wall as a structural part of the new roof to be supported on which will mean we would have to fit new rafters and new roof to shelter.*

*In my opinion the shelter is getting to the point of being unused for safety.*

*Due to where shelter is located you would need to make the necessary arrangements to move position of bus stop whilst work is commencing and will also need barriers around shelter for safety purposes.*

Builder one has provided a quote for the works above.

### **Alternative opinions and quotes**

Two further local builders were contacted to get their opinions of the state of the bus shelter. We believe one has been out to have a look, and we are waiting on their report. The third builder has not responded to our request.

### **Recommendation**

1. Council notes the safety concerns flagged and the need for remedial work.
2. Quotes obtained for making the bus shelter safe are considered at June's meeting.